



www.bigbellysolar.hr






Collection List

Ready to Collect	1 / 28
	0 / 16
	1 / 12

Overflow Status

0 Components
100% Full


Collection Efficiency



Total Liters / 6 months




Recycling Diversion / 6 months



Deployment Map



Collection Summary vs. Baseline / 6 months



Dubrovnik - 28 Bigbelly stations in service

AVERAGE NUMBER
OF PICK-UPS
PER WEEK/STATION



before



now

93%

Increase of collection
efficiency

27%

Recycling rate

Deciding factor – operational cost